GRAND River ENERGY Center
A GRDA Power Generating Facility

Week 53 - Dec 28 2020 - January 3, 2021

Weekly CCR Landfill Inspection Form

Inspection for Structural Weakness on GREC CCR Landfill:
The inspector shall inspect for: surface cracks both transverse or longitudinal; slides, sinkholes, or depressions; missing vegetative cover; animal burrows; vegetation larger than two (2) inches in diameter; accumulated liquid; and surface discoloration indicating ash discharge from the landfill.
Inspection Findings: No Findings
Action Taken: None

Inspection for Excessive Fugitive Dust and Proper Operations to Minimize Fugitive Dust:
Inspection Findings: No Findings
Action Taken: None

Inspected by: Travis Hinshaw

Date: 12/30/2020

Signed: Digitally signed by Hinshaw, Travis Date: 2020.12.30 10:43:15 -06'00'

Reviewed By: Digitally signed by Bednar, Mike Date: 2020.12.30 11:12:05 -06'00'