



Week 10 – March 06<sup>th</sup> – March 12<sup>th</sup>

## Weekly CCR Landfill Inspection Form

### Inspection for Structural Weakness on GREC CCR Landfill:

*The inspector shall inspect for: surface cracks both transverse or longitudinal; slides, sinkholes, or depressions; missing vegetative cover; animal burrows; vegetation larger than two (2) inches in diameter; accumulated liquid; and surface discoloration indicating ash discharge from the landfill.*

#### Inspection Findings:

Surface cracks noted on west side of “active” landfill section due to heavy rain.

#### Action Taken:

Resurfaced the area noted above on 3/15/2023.

### Inspection for Excessive Fugitive Dust and Proper Operations to Minimize Fugitive Dust:

#### Inspection Findings:

None

#### Action Taken:

N/A

Inspected by: Maria Saucedo

Date of Inspection: Wed-03/8/2023

Signed: 