GRAND River ENERGY Center
A GRDA Power Generating Facility

Week 30 - July 22nd - 28th

Weekly CCR Landfill Inspection Form

Inspection for Structural Weakness on GREC CCR Landfill: *The inspector shall inspect for: surface cracks both transverse or longitudinal; slides, sinkholes, or depressions; missing vegetative cover; animal burrows; vegetation larger than two (2) inches in diameter; accumulated liquid; and surface discoloration indicating ash discharge from the landfill.*
Inspection Findings: all findings are good with no problems
Action Taken: none

Inspection for Excessive Fugitive Dust and Proper Operations to Minimize Fugitive Dust:
Inspection Findings: no fugitive dust found
Action Taken: none

Inspected by: Randy Bogle

Date: 07/26/2019

Signed: Bogle, Randy Digitally signed by Bogle, Randy Date: 2019.07.26 09:20:32 -05'00'

Reviewed By: Cornett, Chris Digitally signed by Cornett, Chris Date: 2019.07.29 07:25:29 -05'00'